
Incorrect Label on Side Terminal Junctions of Liftgate Charging Noseboxes

It has been identified that our User Guide had incorrect information referring to the side connections on our DirectTM Plus/Flex/Max systems as well as our new generation SelectTM/DirectTM systems.

The User Guide had the side terminal junctions for the "Interior Light Positive" and "Interior Light Switch" in opposite positions. Please disregard the original User Guide's side terminal junction call out and refer to Figures 1 and 2 below for the CORRECT junction call out. This error has been corrected in Doc 2.01 of the Plus/Flex/Max guide and Doc 1.02 of the Select/Direct guide. We apologize for any inconvenience that this may have caused.



Please contact Purkeys' Technical Services Department if you have any questions. Phone: 479-419-4800 | www.purkeys.net/contact/

